





















Roca

NAIA









 P 	P bar	 MAX 10	
 P 	P bar	MIN 1  5 MAX	 3 2 
  T	°C	 80 MAX.	 65 50 
 Q (3 bar)	l/min	8   5	 20




A5A3096

A5A3296

A5A3396







A5A6096







A5A3996



A5A3D96











A5A3796







A5A3496




5**A5A3596..0**






A5A0296



1 $P > 0,5 \text{ bar}$






2 $P < 0,5 \text{ bar}$







A5A2196






1




2



8



0%




100%



0%














100%



Min. 85



1 - AG0136500R	10 - AG0075300R	19 - A525023600	28 - AG0137000R
2 - AG0085300R	11 - AG0096409R	20 - A525005200	29 - A505400900
3 - A525023507	12 - AG0126900R	21 - AG0001907R	30 - A525005407
4 - A525005007	13 - A525003500	22 - A525005308	31 - AG0117207R
5 - AG0116200R	14 - AG0136800R	23 - AG0137100R	32 - AG0136700R
6 - AG0046600R	15 - AG0110607R	24 - AG0116800R	33 - AG0096509R
7 - A525020600	16 - AG0137200R	25 - AG0137900R	34 - AG0136903R
8 - AG0136603R	17 - A525003600	26 - AG0036800R	35 - AG0033300R
9 - AG0096200R	18 - A525024200	27 - A525005507	





Roca Sanitario, S.A.
Avda. Diagonal, 513
08029 Barcelona
SPAIN
www.roca.com

902
304
848 | 
LÍNEA DE
ATENCIÓN AL
CONSUMIDOR
ESPAÑA

902
400
423 | 
SERVICIO
TÉCNICO
ESPAÑA


productsupport.rs@roca.net
soporteproducto.rs@roca.net